EXHIBIT 20
DATE 1/28/2011
HB 315

HB315 - Revise historic traction boiler inspection and traction license requirements



Right Side of Case Boiler Showing Construction of Butt and Double Strap Joint



Cross Section of Boiler



Fig. 1—Lap Joint



Fig. 2—Butt and Double Strap Joint

Dick Tombrink

2250 N 12th Rd

Worden, MT 59088

690-4080 cell

967-6687 home

dicknsue@nemontel.net