


Mark MET Towers

as per FAA Guidance

**



1. Alternating paint stripes


- Aviation orange & white paint, top to bottom



2. Eight marker balls

3. Guy wire sleeves

- At anchor points



See two YouTube videos on the marking of MET towers at [UNL Web Site](#).
 Or, direct to - [Safety Markings for MET Towers](#)
 And, direct to - [How To Properly Mark MET Towers as per FAA Guidance](#)

**FAA Guidance on Marking MET Towers (Federal Register: Title 14 CFR Part 77, 6/24/11)

1. Seven equal paint stripes of aviation orange and white (top to bottom)
2. Eight spherical marker balls on guy wires (four within 15 feet of the top wire connection to the tower, and four at or below the midpoint of the structure on the outer guy wires)
3. One high visibility sleeve on each guy wire anchor point plus another sleeve on each outer guy wire



A joint venture between UNL Extension and the Nebraska Aviation Trades Association