	T		$\overline{}$	HB190 BRIDGE ACCESS BRIDGE SITE DESCRIPTION									A 1/190. A
Bridge Name	DATE	Name(s) of person	REG	COUNTY	DOT	Stream / River	AT MM	ACCESS FEATURE Bridge Coordinates (Lat. ADJACENT LAND OWNER ADDRESS PHONE					Accessibility Assessment
Droys reins	-	conducting review	1			Stream / River	At Min		Longitude)	Mary Pat Murphy	ADUKESS	NUMBER	Notes Impediment to access: Landowner has no problem with access, in fact, she built her fence so public can access a small plot of her property.
Birch Grove Crossing	7/7/2009	Vashro, L. Anderson	1	Flathead		Whitefish River		Stile	T29N R21W S08	mary racinal proy	875 Birch Grove Road	406-756-7721	Last fall, the grazing lessee contacted FWP because someone had cut the fence in numerous places, allowing his cattle to get out on Birch Grov. Road both directly and by crossing under bridge and coming up on far side. Landowner and lessee were looking for assistance to contain their
irch Grove !A1		Cavigli, Wiersma		Cty Com				☐ Gate			Kalispell, MT 59901		Ilivestock while continuing access.
lick above to see photos)				Brenneman				Roller			Grazing Lease-Roger Doely	406-756-7721	Action: FWP staff obtained a right-of-way permit from Flathead County. FWP then repaired fence, added additional t-posts to reinforce fence, added an additional wood post and half beam to strengthen fence corner and provide spot to pull canoes, etc. over, and constructed a pedestria
				PW Dir Prunty	1	ĺ		Walkover		ł	ļ	406-257-9399	bypass with t-posts and smooth wire to allow access up river bank but contain livestock in event of escape. Reinforced fence up to bridge with wire fence panels. Signed area with access rules.
				ROW Spec				Wooden Rail Fence		1			Estimated Cost: \$173.91 Volunteer Effort/Donated Materials. We had two members of Flathead Wildlife, Inc. and two members of Flathead Chapter of Trout Unlimited
		1		Vernarsky	1	1		Other Description					donate labor for the project. The 4 volunteers worked roughly 2-1/2 hours for a total of 10 hours labor. They drove themselves to the work site which we would estimate would total 75 miles.
North Fork of Black Foot	5/30/2009	Ezra Schwalm	1,		Ø	Blackfoot	-	Stile	 	Jon Krutar		100 700 5007	Impediment to access: A barbed wire fence is empeding raft launching at this site. Landowner contated FWP in a cooperative
	3/30/2003		'			Biackioot	3	Gate			77 Homestead Ln	406-793-5607	spirit & requested an access point in the form of a gate.
Fork Road! A1		Jeff Darrah			Bruce Friede		ł				Ovando, MT 59854		
click above to see photos)		Dan Curtin			544-6807			Roller				}	Action: A gate, 2 posts, a brace post 7 some smooth wire
		Nick Taylor				1	1	Walkover		1		-	Estimated Cost: Less than \$300 00
						}	1	☐ Wooden Rail Fence					Three volunteers: Tim Aldrich, President, Montana Wildlife Fed & Hellgate Hunters & Anglers, Corey Fisher TU
						L		Other Description					
Raymond Bridge	5/30/2009	Ezra Schwalm	2	Ø		Blackfoot River		Stile		Mannix Borther's (Ranch (Randy	106 Spieker Loop	406-793-5834	Impediment to access: Fence was impeding boat access. Landowner contacted FWP in a cooperative spirit & requested an access point in the form of a gate
Raymond Bridge !A1	-	Jeff Darrah		Powell County				☐ Gate		Mannix)	Helmville, MT 59843		access point in the form of a gate
		Dan Curtin		Duane Hoxworth			}	Roller	ĺ		neittviie, WT 59045		
	i	1	1	Duarie Huxworth				Walkover					Action: 2 posts, a gate
	į	Nick Taylor				}		☐ Wooden Rail Fence		•	,		Estimated Cost: Less than \$300.00
							1						Three volunteers: Tim Aldrich, President, Montana Wildlife Fed & Hellgate Hunters & Anglers, Corey Fisher TU
 -	 	 	+	ļ	 	 	↓	Other Description	<u> </u>	Dat Biret	 		
Edwards Road	6/7/2009	Doug Johnson	2	Ø		Bitterroot River		☐ Stile	ļ	Bob Birch	Sula, MT	406-821-4035	Impediment to access: Fallin down fences
astfork of Bitterroot River		Lou Royce		Ravalli County		ł		☐ Gate	}	Sula Peak Ranch			Action: Fence posts and rails - 1/2 dozen each
Edwards Road!!A1		Joe Jaquith		Bill Misner		1		Roller		Jerry Ehmann	Sula, MT	406-821-3407	Estimated Cost: \$81.50
1	1			contacted & he	}	1	-	Walkover			(very cooperative landowners)		Volunteers: 6 from Ravalli Cty FW Assoc. Trout Uni, FOAM, Earl & Scott Little (Ravalli Cty FW),
				was okay w/				☑ Wooden Rail Fence	į		(vary cooperative idinariment)		1
		ļ		oreject				Other Description					Fred Upchurch (Ravalli Cty FW), Eddi Olwell (FOAM), Geoff Fitzgerald (Trout Unlimited), John Wasson (Ravalli Cty FW),
Dunner Bistolet		 	+-		 		 	Stile		 -	 	 	Joe Hundley (Ravalli Cty FW)
Duncan District	4/17/2009	Will Murray	3		-	Ruby	ł		N45deg.26.034min.		1		Single Lane Bridge - parking should be reviewed
		Dave Delisi						Gate	W112deg.15.438min.			}	NE Corner access is ok - best current access
		Jerry Kustich				1	1	Roller				1	NW Corner is blocked by fence topped with strand of barbed wire
		John Eisenbarth				}		Walkover	1				SW corner access is ok but could be improved by removing barbed wire in way
				j		}	1	☐ Wooden Rail Fence	}				SE Access is obstructed by debris
			<u>L</u> _					Other Description	1				Notes: Remove barbed wire at SW corner; find place for creation of road-pullout for 2 vehicles within walking distance.
Lewis Lane	4/17/2009	Will Murray	3			Ruby		Stile	N 45 deg. 28.128 min.				Parking may be adequate for 1 car at position SE of bridge; large area near bridge that looks like pullout, but is actually a water hydrant and is clearly labeled "No Parking" - this is potential area for conflit of people
		Dave Delisi				} ~~	}	Gate					River access difficult at three of four corners, although stile at SE corner might make access possible there. A gate has recently been added a
	}							Roller	W112deg.18.139min.				SW corner which provides easy access to that corner. Curiously, dead animals (cat, raccoon, & skunks) had been placed at each corner so one accessing river from bridge would have to walk over
		Jerry Kustich			-	ł		Walkover		į	-		around
		John Eisenbarth				1						}	Gunshots hear while we inspected bridge
		1				}	1	Wooden Rail Fence					Notes: Clean up the area.
	 		-	 _		 -	 	Other Description	ļ	 	ļ	 	
Silver Spring	4/17/2009	Will Murray	3			Ruby		☐ Stile	N45deg.24.685.min	}			Safe as is.
	ì	Dave Delisi					Ì	☐ Gate	W112deg.12.341min.	1			Currently maintained as an Access Site; parking is excellent and access to river is also good.
		Jerry Kustich	1			1		Roller					It must be noted that, as with all FAS along the Ruby, Sliver Spring is a temporary Access Site permitted by the current landowner. Should landowner change hands, as happened at Coy Brown Bridge FAS, the public may lose access to that site.
		John Eisenbarth				1		☐ Walkover					
		i Lisenoal III				}		☐ Wooden Rail Fence					Vigilance should be paid to sensure Access Sites such as Silver Spring and Alder Bridge are not lost.
		1	-		ļ			1					
		1		<u></u>	L	L	1	Other Description	J		(

HB190 BRIDGE ACCESS BRIDGE SITE DESCRIPTION Accessibility Assessment Name(s) of person Bridge Name REG DATE COUNTY DOT Stream / River AT MM ACCESS FEATURE ADJACENT LAND OW **ADDRESS** Notes NUMBER Ken & Ginny Stile Accessibility Assessment: The landowners of the adjacent property to this bridge have been faced with littering and occassonal destruction of Loma Bridge 9/8/2009 Woody Baxter Missouri River 739-4323(H) barbed-wire fence by the public. Throught the years, and most recent, the owners have complained to FWP of what they perceive as illegal Ritland campfires and trespassing on property. Existing layout of the site does not provide the public with safe parking along the county road, nor easy Loma Bridge!!A1 R-4 & R-6 Parks Cty Comm. walking access through the fences that connects to the bridge abutments. Action: Repair (upgrade) the barbed-wire fence down by the bridge abutment, and portion of the fence which runs parallel to the county Rolle Jim O'Hara road. both sides, Provide walk-through gates, w/ springs, with a designated area for parking & close-off an area where parking is unsafe. Added regulatory signs "NO PARKING BEYOND THIS SIGN", "STAY BELOW THE ORDINARY HIGH WATER MARK", PACK-IN/PACK-OUT" ☐ Walkover Road Super Estimated Cost: \$1,000 00 Parking should be reviewed. Wooden Rail Fence Bill Scheele Volunteers/Cost Share/Donations: Landowner, County Commissioner, County Road Supervisor, FWP R-4 Supervisors Warden Other Description Captain Warden Sergeant Fisheries Parks Maintenance Parks Manager Inf & Prog Manager Impediment to access: Deterorating condition of fence (existing walk thru gate) and height/composition of extising fence made delivery of float 4 ☐ Stile Dearborn 5/1/2009 Bryan Golie, et.al. earborn River Dearborn Ranch Wolf Creek, MT ☑ Gate No contact US Hwy 287 Rocky Harber - Mor Action: Materials, improvements (see photos) Roller Lewis & Clark Cty Estimated Cost: Donated materials by Dearborn Ranch ☐ Walkover Volunteers/Cost Share/Donations: 5 volunteers including ranch manager expended efforts in one day to complete job. Wooden Rail Fence Other Description 1 Nitche Road Bridge 7/7/2009 ☑ Stile Gary Hammond 45.48629 -109.45602 Campbell, Wallace L 21 Nitche Rd 406-328-4056 Impediment to access: existing stiles in disrepair Nitche Creek'!A1 8/7/2009 Cleve Schuster Stillwater Stillwater River ☐ Gate & Wendelin Absarokee MT 59001-6311 Action: reset and reattach existing rails in existing stiles on both sides of river Roller Parks Maintenance Ken Kistler Estimated Cost: \$0 - 20 minutes of labor Walkover This is a fairly new bridge, which had adequate acce4ss added at construction. Downed rails in stiles made access difficult. Repairs Co Rd returned stiles to their original condition. All repair work was done within existing rights of way and with existing materials. Wooden Rail Fence Superintendent Other Description **V** Stile Spring Creek Bridge 3/12/2009 Gary Hammond, Jerry 45 31.814 -109.636 407 W Grove St Arnold Green Meadow 406-328-4395 Impediment to access: Steep, hazardous, rocky, slick embankments with barbed wire and woven wire attached to bridge abutments Action: First, FWP arranged for sportsmen to park in the Spring Creek Community Center lot north of the bridge. Signs were ☐ Gate Spring Creek!!A1 mons, Cleve Absarokee MT 59001-6205 posted. Acquired a 124 permit. Contacted local telephone coop, which sent a lineman to mark underground lines. On northwest corner, installed steel gate and built re-enforced gravel trail down steep bank. On northeast corner, built and installed pressure-Roller Catherine F Conner 63 Spring Creek Rd 406-328-4396 treated wooden stairs down embankment and wooden ladder over fence. At southeast corner, will install swinging steel gate in rail Estimated Cost: \$350 plus labor ☐ Walkove Ken Frazier, Bob Gibson Flyfishers and Billings Rod & Gun Club donated money for gates and labor. 4-H member helped with labor. Absarokee MT 59001-6222 Notes: Northwest and northeast corners of the bridge were steep, rocky, slick, hazardous and virtually impassable. People had Wooden Rail Fence Jerry Simmons, Don Kent & M Ann Johnson P O Box 777 climbed over loose barbed wire fence on northwest corner, but access was dangerous. At southeast corner, people were trespass on ag land to access river. Parking near bridge is minimal and blocks busy county road. Other Description Absarokee MT 59001-0777 Stile East Rosebud Bridge 8/12/2009 Mule', Watson, East Rosebud River 45 18.482 -109 31.515 State of Montana Impediment to access: Fences attached to the bridge abutment Action: Contacted local telephone coop, which sent a lineman to mark underground cables. Installed steel swinging gates on new wooden posts ☑ Gate E Rosebud 'A1 Nixdorf, Hammond, Carbon in existing fences on the southeast and southwest corners of the bridge/river interesection. Repaired rail and barbed wire fences that attached to Roller Gibson, Frazer ☐ Walkover Estimated Cost: \$200 in materials Volunteers: Billings Rod & Gun Club and Magic City Flyfishers donated for materials. Inv Wilke, president of the Billings Rod and ✓ Wooden Rail Fence Gun Club, helped with labor Other Description mpediment to Access: Build short streach of fence (75' to 100') and creat a <- type opening for people to walk through fence. Tighten up short v ☐ Stile **Bundy Bridge** 6/12/2009 Kevin Holland ellowstone River 45.99769 -108.00900 Janet Talcott Bundy Road 406-967-2184 section of fence (75' to 100') previoulesy damaged by sportsmen using river Gate Bundy Bridge!! A 1 Yellowstone Ctv Worden MT 59088 Action: rebuild fence and include walk through gap.

Page 2 HB190 BRIDGE ACCESS WORK 9/9/2009

Estimated Cost: \$100 plus time to do work

locators called ahead of project.

Volunteers: all work and materials will be provided by MT FW&P

Notes: Construction by FWP staff with help from Billings Rod & Gun Club and PLWAA. County commissioners and legislator attended. Line

Roller

Walkover


Wooden Rail Fence

Other Description

im Reno

Cty Comm.

John Ostlund



Pre-project Footpath to right of Whitefish River sign.



Vandalized Fence. Private property to left of fence available for public use



Warden Captain Lee Anderson posting public use rules.

BIRCH GROVE CROSSING, WHITEFISH RIVER, FLATHEAD COUNTY

NE Corner of Birch Grove Bridge, public uses county right--of-way to access Whitefish River




Flathead Wildlife & Flathead Chapter Trout Unl volunteers rebuilding bridge



Warden Captain Lee Anderson building pedestrian bypass










Access was put on Southeast corner / boat put in. North Fork of Blackfoot River where it intersects MT Hwy 200, located in Powell County

NORTH FORK ROAD BRIDGE



Before




After

NITCHE CREEK BRIDGE




Retore


After
BUNDY BRIDGE - YELLOWSTONE COUNTY



LOMA BRIDGE SE of Loma MT off of the Loma Bridge Road Crosses the Missouri River.



SPRING CREEK BRIDGE - STILLWATER COUNTY



EAST ROSEBUD RIVER BRIDGE