

Montana Board of Oil and Gas Conservation Environmental Assessment

Operator: Oasis Petroleum North America LLC
Well Name/Number: Betsy Federal 2758 24-29H
Location: SE NE Section 29 T27N R58E
County: Roosevelt, MT; Field (or Wildcat) Wildcat (Bakken Horizontal)

Air Quality

(possible concerns)

Long drilling time: No, 30-40 days drilling time.

Unusually deep drilling (high horsepower rig): Triple derrick drilling rig to drill a single lateral horizontal Bakken Formation test, 20,504' MD/10,368' TVD.

Possible H₂S gas production: Yes, slight H₂S possible.

In/near Class I air quality area: No Class I air quality area nearby.

Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required under 75-2-211.

Mitigation:

Air quality permit (AQB review)

Gas plants/pipelines available for sour gas

Special equipment/procedures requirements

Other: _____

Comments: If there are existing pipeline for natural gas in the area then gas must be tied into system or if no gathering system nearby associated gas can be flared under Board Rule 36.22.1220.

Water Quality

(possible concerns)

Salt/oil based mud: Yes to oil based invert drilling fluids for intermediate casing hole. Horizontal hole will be drilled with saltwater. Surface casing hole will be drilled with freshwater and freshwater mud system.

High water table: No high water table anticipated.

Surface drainage leads to live water: Yes, closest drainage is an unnamed ephemeral tributary drainage to the Missouri River, off location to the south from this location. Within the ephemeral drainage, there is a stock pond.

Water well contamination: No, closest water wells are about 3/8 of a mile to the north, about 3/4 of a mile to the east northeast, about 3/4 of a mile to the southeast and about 7/8 of a mile to the south from this location. Depth of these stock and domestic wells are 45' to 1450'. The operator on his permit to drill indicated that they were setting 1670' of surface casing. This amount of casing will not cover the Base of the Fox Hills Formation. To cover the Base of the Fox Hills Formation, the operator should set 1767' of surface casing. This well will be drilled with freshwater and freshwater mud to 1,767' and steel surface casing will be run and cemented to surface to protect groundwater.

Porous/permeable soils: No, sandy silty clay soils.

Class I stream drainage: Yes, Class I stream drainage is the Missouri River.

Mitigation:

Lined reserve pit

Adequate surface casing

Berms/dykes, re-routed drainage

Closed mud system

Off-site disposal of solids/liquids (in approved facility)

Other: _____

Comments: 1,767' surface casing will be drilled with freshwater, steel casing will be run to 1,767' and cemented back to surface, to protect freshwater zones in adjacent water wells, also covering the Fox

Hills aquifer. Adequate surface casing and operational BOP equipment will prevent problems.

Soils/Vegetation/Land Use

(possible concerns)

Steam crossings: None anticipated.

High erosion potential: Yes high erosion potential , location will require a moderate cut of up to 22.9 and a moderate fill of up to 24.2', required.

Loss of soil productivity: No, location to be restored after drilling, if nonproductive. If productive unused portion of this drillsite will be reclaimed.

Unusually large wellsite: No, large well site 430'X320'

Damage to improvements: Slight surface use appears to be grassland.

Conflict with existing land use/values: Slight

Mitigation

Avoid improvements (topographic tolerance)

Exception location requested

Stockpile topsoil

Stream Crossing Permit (other agency review)

Reclaim unused part of wellsite if productive

Special construction methods to enhance reclamation

Other Requires DEQ General Permit for Storm Water Discharge Associated with Construction Activity, under ARM 17.30.1102(28).

Comments: Access will be over existing county roads and existing well access road. About 3819' of new access road will be built into this location off the existing well access road. Oil based invert drilling fluids will be recycled. Completion fluids will hauled to a commercial Class II disposal. Cuttings and solids will be buried/solidified on site in the lined reserve pit. The pit will be allowed to dry and the pit backfilled. No concerns.

Health Hazards/Noise

(possible concerns)

Proximity to public facilities/residences: Nearest residence is about 1 3/8 of a mile to the northeast from this location. The Town of Bainville, Montana is about 5.1 miles to the northeast from this location.

Possibility of H2S: Yes, slight from Mississippian Formations.

Size of rig/length of drilling time: Triple drilling rig 30 to 40 days drilling time.

Mitigation:

Proper BOP equipment

Topographic sound barriers

H2S contingency and/or evacuation plan

Special equipment/procedures requirements

Other: _____

Comments: Adequate surface casing cemented to surface with working BOP stack should mitigate any problems.

Wildlife/recreation

(possible concerns)

Proximity to sensitive wildlife areas (DFWP identified): None identified.

Proximity to recreation sites: None identified.

Creation of new access to wildlife habitat: No

Conflict with game range/refuge management: No

Threatened or endangered Species: Species identified as threatened or endangered are the Pallid Sturgeon, Interior Lease Tern, Whooping Crane and Piping Plover. Candidate species is the Sprague's Pipit. NH tracker website indicates zero(0) species of concern.

Mitigation:

- Avoidance (topographic tolerance/exception)
- Other agency review (DFWP, federal agencies, DSL)
- Screening/fencing of pits, drillsite
- Other: _____

Comments: Private surface land. There maybe species of concern that maybe impacted by this wellsite. We ask the operator to consult with the surface owner as to what he would like done, if a species of concern is discovered at this location. The Board of Oil & Gas has no jurisdiction over private surface lands.

Historical/Cultural/Paleontological

(possible concerns)

Proximity to known sites: None identified.

Mitigation

- avoidance (topographic tolerance, location exception)
- other agency review (SHPO, DSL, federal agencies)
- Other: _____

Comments: Private surface land. There maybe possible historical/cultural/paleontological sites that maybe impacted by this wellsite. We ask the operator to consult with the surface owner as to his desires to preserve these sites or not, if they are found during construction of the wellsite. The Board of Oil & Gas has no jurisdiction over private surface lands.

Social/Economic

(possible concerns)

- Substantial effect on tax base
- Create demand for new governmental services
- Population increase or relocation

Comments: Wildcat well. No concerns

Remarks or Special Concerns for this site

An exploratory single lateral horizontal Bakken Formation test: 20,504'MD/10,368'TVD.

Summary: Evaluation of Impacts and Cumulative effects

No long term impacts expected, some short term impacts will occur, but can be mitigated.

I conclude that the approval of the subject Notice of Intent to Drill (does/**does not**) constitute a major action of state government significantly affecting the quality of the human environment, and (does/**does not**) require the preparation of an environmental impact statement.

Prepared by (BOGC): /s/Steven Sasaki

(title:) Chief Field Inspector

Date: March 30, 2012

Other Persons Contacted:

Montana Bureau of Mines and Geology, GWIC website
(Name and Agency)
Roosevelt County water wells
(subject discussed)
March 30, 2012
(date)

US Fish and Wildlife, Region 6 website
(Name and Agency)
ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA
COUNTIES, Roosevelt County, Montana
(subject discussed)
March 30, 2012

Montana Natural Heritage Program Website
(Name and Agency)
Heritage State Rank= S1, S2, S3, Location T27N R58E
(subject discussed)
March 30, 2012
(date)

If location was inspected before permit approval:
Inspection date: ____
Inspector: _____
Others present during inspection: _____