

**Montana Board of Oil and Gas Conservation
Environmental Assessment**

Operator: Continental Resources, Inc.
Well Name/Number: Thomas 3-27H
Location: SE SW Section 27 T23N R56E
County: Richland, **MT;** **Field (or Wildcat)** W/C (Bakken Horizontal)

Air Quality

(possible concerns)

Long drilling time: No, 30 to 40 days drilling time.

Unusually deep drilling (high horsepower rig): No, triple derrick rig to drill a single lateral horizontal Bakken Formation test, 19,924'MD/10,438'TVD.

Possible H2S gas production: Slight chance H2S gas from Mississippian Formations.

In/near Class I air quality area: No Class I air quality area nearby.

Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required under 75-2-211.

Mitigation:

Air quality permit (AQB review)

Gas plants/pipelines available for sour gas

Special equipment/procedures requirements

Other: _____

Comments: No special concerns – using triple rig to drill a single lateral horizontal Bakken Formation test, 19,924'MD/10,438'TVD. If there is an existing pipeline for gas in the area, then associated gas can be gathered or if no gathering system nearby gas can be flared under Board Rule 36.22.1220.

Water Quality

(possible concerns)

Salt/oil based mud: Yes to intermediate casing string hole to be drilled with oil based invert drilling fluids. Horizontal lateral will be drilled with brine water. Surface casing hole will use freshwater and freshwater mud system (Rule 36.22.1001).

High water table: None anticipated.

Surface drainage leads to live water: Yes, nearest drainage is an unnamed ephemeral tributary to Fox Creek, about 1/8 of a mile north from this location. Within this drainage there is a large stock pond, about 7/8 of a mile to the northeast from this location.

Water well contamination: None anticipated, closest water wells are about ¼ of a mile to the west and about ¾ of a mile to the east northeast from this location. Depth of these stock water wells range from 35' to 64'. Surface hole will be drilled with freshwater and freshwater mud system, Rule 36.22.1001. Surface casing will be set at 2010' and steel casing set and cemented to surface from 2010'.

Porous/permeable soils: No, silty-sandy clay soils.

Class I stream drainage: No Class I stream drainages in the area of review.

Mitigation:

Lined reserve pit

Adequate surface casing

Berms/dykes, re-routed drainage

Closed mud system

Off-site disposal of solids/**liquids** (in approved facility)

X Other: Lined cuttings pit will be used since this is a closed loop mud system to be employed.

Comments: Require 2010' of surface casing be set to cover the base of the Fox Hills and cemented to surface adequate to protect freshwater zones, Rule 36.22.1001.

Soils/Vegetation/Land Use

(possible concerns)

Stream crossings: No stream crossings required.

High erosion potential: Possible high erosion potential on cut and fill slopes. This location will require a moderate cut, up to 19.3' and a moderate fill, up to 16.8'.

Loss of soil productivity: No, location will be restored after drilling if unproductive. If productive, unused portion of this drilling location will be restored.

Unusually large wellsite: A large wellsite, 400'X450' required.

Damage to improvements: Slight

Conflict with existing land use/values: Slight, surface use appears to be cultivated land.

Mitigation

Avoid improvements (topographic tolerance)

Exception location requested

Stockpile topsoil

Stream Crossing Permit (other agency review)

Reclaim unused part of wellsite if productive

Special construction methods to enhance reclamation

Other _____

Comments: Access will be over existing county road, #334 and existing lease road. About 229' of new access road will be built into this location off the existing lease road for the Marlys 1-34H. Cuttings will be buried in the lined cuttings pit. Oil based drilling fluids will be recycled. Completion fluids will be hauled to a commercial SWD disposal. The lined cuttings pit will be allowed to dry and then closed by filling and mixing with clay subsoils. Minimum of 4' of cover over the top of the cuttings. No special concerns.

Health Hazards/Noise

(possible concerns)

Proximity to public facilities/residences: Closest residences are about 1.125 miles to southwest, about 1.875 miles to the northeast and about 2 miles to the northwest from this location.

Possibility of H2S: Slight chance from Mississippian Formations.

Size of rig/length of drilling time: Triple drilling rig/short 30 to 40 days drilling time.

Mitigation:

Proper BOP equipment

Topographic sound barriers

H2S contingency and/or evacuation plan

Special equipment/procedures requirements

Other: _____

Comments: Adequate surface casing cemented to surface with an operational BOP stack (annular and double ram rated for 5,000 psig) should mitigate any problems, Rule 36.22.1014.

Wildlife/recreation

(possible concerns)

Proximity to sensitive wildlife areas (DFWP identified): Fox Lake State Game Management Area, about 5.4 miles to the southwest from this location.

Proximity to recreation sites: Fox Lake State Game Management Area, about 5.4 miles to the southwest from this location.

Creation of new access to wildlife habitat: No new access to wildlife habitat.

Conflict with game range/refuge management: No

Threatened or endangered Species: Species identified as threatened or endangered are the Pallid Sturgeon, Interior Least Tern, Whooping Crane and Piping Plover.

Candidate species are the Sprague's Pipit and the Greater Sage Grouse. NH tracker website indicates one (1) species of concern, the Whooping Crane.

Mitigation:

Avoidance (topographic tolerance/exception)

Other agency review (DFWP, federal agencies, DSL)

Screening/fencing of pits, drillsite

Other: _____

Comments: Private cultivated surface lands. There maybe species of concern that maybe impacted by this wellsite. We ask the operator to consult with the surface owner as to what he would like done, if a species of concern are discovered at this location.

Historical/Cultural/Paleontological

(possible concerns)

Proximity to known sites None identified.

Mitigation

avoidance (topographic tolerance, location exception)

other agency review (SHPO, DSL, federal agencies)

Other: _____

Comments: Private cultivated surface lands. There maybe possible historical/cultural/paleontological sites that maybe impacted by this wellsite. We ask the operator to consult with the surface owner as to his desires to preserve these sites or not, if they are found during construction of the wellsite.

Social/Economic

(possible concerns)

Substantial effect on tax base

Create demand for new governmental services

Population increase or relocation

Comments: No concerns

Remarks or Special Concerns for this site

No, special concerns for drilling this single lateral horizontal Bakken Formation test, 19,924'MD/10,438'TVD.

Summary: Evaluation of Impacts and Cumulative effects

No significant long term impacts expected, some short term impacts will occur.

I conclude that the approval of the subject Notice of Intent to Drill (does/**does not**) constitute a major action of state government significantly affecting the quality of the human environment, and (does/**does not**) require the preparation of an environmental impact statement.

Prepared by (BOGC): /s/Steven Sasaki
(title:) Chief Field Inspector
Date: October 23, 2012

Other Persons Contacted:

Montana Bureau of Mines and Geology, GWIC website
(Name and Agency)

Water wells in Richland County
(subject discussed)
October 23, 2012
(date)

US Fish and Wildlife, Region 6 website
(Name and Agency)
ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES
MONTANA COUNTIES, Richland County
(subject discussed)
October 23, 2012
(date)

Montana Natural Heritage Program Website
(Name and Agency)
Heritage State Rank= S1, S2, S3 T23N R56E
(subject discussed)
October 23, 2012
(date)

If location was inspected before permit approval:
Inspection date: _____
Inspector: _____
Others present during inspection: _____