

Montana State Legislature

Exhibit No.


9

This exhibit was not scanned because it is a pamphlet, the front cover is scanned to aid in your research. The exhibit is on file at the Montana Historical Society and may be viewed there.

EXHIBIT
DATE 01/06/05
#15

SALINITY CONTROL

in Montana



Before Photo. A large flowing saline seep in a crop-fallow field in 1996 prior to any reclamation measures. Photo corresponds to Well 8 in Figure 6.



After Photo. Same saline-affected area in 2000 after the recharge area had been identified through a ground water investigation. The recharge area was rotated to a alfalfa-grass mixture and later the seep perimeter seeded to salt-tolerant grass species.