



STATUS OF ACTIVELY MANAGED SITES

Report Printed July 14, 2008

ENVIRONMENTAL QUALITY COUNCIL
JULY 14, 2008
EXHIBIT 5

ACTIVELY MANAGED SITES IN THE CECRA PROGRAM : TOTAL = 33

Site Name	SAA	NOT	VCP*	RI	SRI	HRA	IA	TS	FS	PP	ROD	RD	RA	O and M	ORDER
Beaver Wood Products Inc															
Big West Oil Refinery															
Bitterroot Valley Sanitary Landfill															
Bozeman Solvent Site															
Burlington Northern Fueling Facility Havre															
Burlington Northern Fueling Facility Missoula															
Burlington Northern Fueling Facility Shelby			1												
Burlington Northern Fueling Facility Whitefish															
Burlington Northern Livingston Shop Complex															
Carter Oil Refinery															
CMC Asbestos Bozeman			3												
Davis Post Yard															
Diamond Asphalt Co															
Georgetown Railroad															
Granite Timber Co															
Great Falls International Airport MTANG															
Hart Oil Refinery			5												
Joslyn Street Tailings			2												
Kalispell Pole and Timber															
MDOT Maintenance Facility Helena			1												
Miles City Railyard															
Milwaukee Roundhouse			2												
Mission Wye															
Missoula Sawmill			4												
Missoula White Pine Sash Co															
Reliance Refining Co															
Rhodia Maiden Rock Mine															

FS = Feasibility Study
HRA = Risk Assessment
IA = Interim Action
NOT = Notice Letter
NOV = Notice of Violation Letter
OandM = Operation and Maintenance
ORDER = Orders/CDs/Settlement Agreements
PP = Proposed Plan

RA = Remedial Action
RD = Remedial Design
RI = Remedial Investigation
ROD = Record of Decision
SAA = Site Assessment Activities
SRI = Supplemental Remedial Investigation
TS = Treatability Study

= Action completed = Action in progress

*Numbers in VCP column represent the total number of VCP's submitted for the site.

All data generated from the Montana Department of Environmental Quality, Remediation Division, Site Response Section database on the date shown at the top of the report. Not all data is reflected in the database. Data that has recently been collected and/or changed may not be reflected in the results due to data entry time lag.



STATUS OF ACTIVELY MANAGED SITES

Report Printed July 14, 2008

ACTIVELY MANAGED SITES IN THE CECRA PROGRAM : TOTAL = 33

Site Name	SAA	NOT	VCP*	RI	SRI	HRA	IA	TS	FS	PP	ROD	RD	RA	O and M	ORDER
S & W Sawmill	Completed	Completed		Completed		In Progress	Completed	In Progress							
Tank Hill	Completed			In Progress	In Progress	In Progress	Completed								Completed
Texaco Sunburst Works Refinery	Completed		3	In Progress	In Progress	Completed	In Progress	In Progress	In Progress	In Progress				In Progress	Completed
Tucson Hebrew Academy Cut Bank AFB	Completed						Completed								
Upper Blackfoot Mining Complex	Completed		2	In Progress			In Progress						Completed		Completed
Yale Oil Corp Kalispell	Completed	Completed		In Progress		Completed	Completed	Completed	In Progress	In Progress					

FS = Feasibility Study
 HRA = Risk Assessment
 IA = Interim Action
 NOT = Notice Letter
 NOV = Notice of Violation Letter
 OandM = Operation and Maintenance
 ORDER = Orders/CDs/Settlement Agreements
 PP = Proposed Plan

RA = Remedial Action
 RD = Remedial Design
 RI = Remedial Investigation
 ROD = Record of Decision
 SAA = Site Assessment Activities
 SRI = Supplemental Remedial Investigation
 TS = Treatability Study

 = Action completed  = Action in progress

*Numbers in VCP column represent the total number of VCP's submitted for the site.

All data generated from the Montana Department of Environmental Quality, Remediation Division, Site Response Section database on the date shown at the top of the report. Not all data is reflected in the database. Data that has recently been collected and/or changed may not be reflected in the results due to data entry time lag.